



SERVICE BULLETIN

QUALITY INFORMATION ANALYSIS
OVERSEAS SERVICE DEPT. MITSUBISHI MOTORS CORPORATION

SERVICE BULLETIN		No.: MSB-99E11-003	
		Date: 2000-05-31	<Model>
Subject: CHANGE IN 4G1 ENGINE CRANKSHAFT PULLEY		(EC)COLT/LANCER (CK, CJ)	99-10 99-10
Group: ENGINE	Draft No.: 99EN573119		(EC)SPACE STAR (DG1A,DG5A)
INFORMATION/ CORRECTION	INTERNATIONAL CAR ADMINISTRATIO OFFICE	<i>Tomoki Nitta</i> T.NITTA - PROJECT LEADER AFTER SALES SERVICE & CS PROMOTION	

1. Description:

For reduced weight of the 4G1 engine crankshaft pulley, the crankshaft pulley has been changed as described below.

2. Interchangeability:

Interchangeability provided that use of the new crankshaft pulley is recommended for replacement.

3. Effective Date:

From February 12, 1999 (From YD 2146)

4. Details:

The hatched portion of the crankshaft pulley has been changed to be made of sheet metal for reduced weight of the pulley. Also, the spacer has been added.

