

SERVICE BULLETIN


OVERSEAS SERVICE DEPT. MITSUBISHI MOTORS CORPORATION

| SERVICE BULLETIN | | | | No.: MSB-99E23-003 | | |
|------------------|---|--|-----|---|-----------------|--------------|
| | | | | Date: 2000-29-02 | <model></model> | <m y=""></m> |
| Subject: | ject: DELETION OF AUTOMATIC TRANSMISSION EXTERNAL OIL FILTER | | | | ALL MODELS | 99-99 |
| Group: | AUTOMATIC D TRANSMISSION | | Dra | aft No.: 99AT610110 | | |
| INFORMATION | | INTERNATIONAL CAR ADMINISTRATION OFFICE | | NITTA - PROJECT LEADER FTER SALES SERVICE & CS PROMOTION | | |

1. Description:

On the front engine front wheel drive (E-W) cars, the external oil filter for the automatic transmission has been deleted.

Deletion of the external oil filter makes it unnecessary to regularly replace the oil filter.



2. Applicable Models:

F4A41, F4A42, F4A51, F5A42, F5A51 W4A41, W4A42, W4A51, W5A42, W5A51

3. Effective Date:

From September 20, 1999